## FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020 District: Vatna Division: Patra Length (km): 2,50.					
-	rerra		ethis to Parsavillage		
		MAINTENANCE	es, is to fact the fee		
	No.: MR-N/201		Road Id No.:		
Status of	the Project:   C	ongoing/Complete	ed/Under Maintenance		
Work is	a case of:	lew Connectivity/	Up gradation/ Maintenance		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement			. 2	
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No /	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No /	
g)	Compaction of flank/slope & raincuts if any			Yes/No /	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others			No.	

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	<i>a</i> )
Unsatisfactory (U)	

NAME: Jai Arakash Singh.
DESIGNATION: J.E.