

FIELD INSPECTION REPORT

Just started

Date of Inspection :	02.12.20	District:	Kaimur
Division :	Bhabua	Length (km):	1.850 km
Name of the Road:	Hansrew Lohdgn Canal Link road to Hansrew		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/2019220/01	Road Id No.:	10108577
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U —
b)	Condition of Surfacing	S/U —
c)	Riding Quality	S/U —
d)	Road Camber	S/U —
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No —
f)	Contraction Joints provided or not (CC Pavement)	Yes/No —
g)	Compaction of flank/slope & raincuts if any	Yes/No —
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U —
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U —
c)	Condition of railings/slab/approach for Bridges	S/SRI/U —
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

(Signature) 02.12.20

NAME: Mukesh Kumar

DESIGNATION: JE