

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Rohtas.
Division : R.W.D Bixamganj	Length (km): 6.85 km.
Name of the Road: Bally to Kosi Link Path Li) Ladui more to Pasra more	
Scheme/Programme: MAINTENANCE New Policy - 2018	Li) Ladui more to Pasra more
Package No.:	Road Id No.: 13/31.0/0 257
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Lisoud Village

SL No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	only sign board fitted E/W being done	S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N.A	Yes/No
g)	Compaction of flank/slope & raincuts if any	Being done	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	only sign board	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		N/O

To be done

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

R. Patel.
03/12/2020
(Signature) JC

NAME: Rakesh Patel

DESIGNATION: