

Hande
3-550
00
)
EA

FIELD INSPECTION REPORT

Date of Inspection : - 3.12.2020 District: - Nalanda.
Division : - Rajgir. Length (km): - 0.700 k.M
Name of the Road: - NH-31 to Raistar.
Scheme/Programme: MAINTENANCE (3054 MR New Maintenance Policy - 2018)
Package No.: - RM/NA/RAJ/19/005. Road Id No.: - 1291010300.
Status of the Project: Ongoing/Completed/Under Maintenance **Not started.**
Work is a case of: New Connectivity/Up gradation/ Maintenance **Maintenance**

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/I
b)	Condition of Surfacing	S/I
c)	Riding Quality	S/I
d)	Road Camber	S/I
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)


3.12.20
(Signature)

NAME:- Kishor Kumar
Assis. Engr
Giriyak.