

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020 District: Nalanda
 Division : HARNAUL Length (km): 2.40 KM
 Name of the Road: Noor Sarai Bhaganbigha Path to village Nosera
 Scheme Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance
 Work is a case of: ☐ New Connectivity ☐ Up gradation ☒ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	☒ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign ☒ boards/informatory/cautionary Board/km & 200m stones/Pavement road markings ☒ are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	in Progress

Overall Rating :

Satisfactory (S) ☒	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ajay Kumar Verma
 03-12-2020
 (Signature)

NAME: AJAY KUMAR VERMA
 DESIGNATION: JUNI