FIELD INSPECTION REPORT

	nspection:	02/12/2020	District:	ROH.	rns
Division: Paircramgan			Length (km):	1.8	
Name of the Road: SHI PUR HALT (PMUSY ROAD) TO				SHIVPUR	
L'eneme,	Togiamme.	MAINTENANCE			
Package No.: Road Id No.: 13 Status of the Project: Ongoing/Completed/Under Maintenance				13/02	1499
Work is a		Now Complete	ted/Under Maintenance		
ATTACAMENTATION	Case of:	the contraction and the property of the contraction	//Up gradation/ Maintenan	e	and a
Sl. No.	4 / S S - 1	Parameters	to be checked	The last	Romark
1.	Pavement				
a)	Road Junction condition				S/U
b)	Condition of Surfacing (warm in hat)				87 4
c)	Riding Quality				<i>-81</i> U
d)	Road Camber				UNS)
	Whether free from defects such as visible cracks, expaggregates in case of CC Pavement.				Yes/No
	Contraction Joints provided or not (CC Pavement)				Yes/No
g) (Compaction of flank/slope & raincuts if any				Yes/No
1.459060-140-60	2. Cross Drainage				
THE RESERVE THE PARTY OF THE PA	Condition of head walls in Hume pipe culverts including its pain				S/SRI/U
	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
	Condition of railings/slab/approach for Bridges				S/SRI/U
	Road Furniture				
THE TABLE	Whether sign boards/informatory/cautionary Board/km & 20 stones/Pavement road markings are provided and maintained				Yes/No
	ompliance His	STREET, SHIP OF THE			14/26
	atus of ATR's				
a) Oi		Profit Control of the			
verall Rati	ing : [Satisfactory (S)			9
		Satisfactory but i	requires Improvement (S	SRI)	
		Unsatisfactory (U	J)		
	L				
					201
				01/1/201	
				(Sign:	ature)
1CH A NOCH	A PANJET				
ME:					

Scanned by CamScanner