## FIELD INSPECTION REPORT

Date of	Inspection: 02	211212020	District:	ROHTE	95	
Division: (Palexamena) Length (km):			1.8			
Name of			war Road (Dhangai)	to Revi	ya via Sadar	Hospital
		MAINTENANCE				
	cknge No.: Road Id No.:			13131021500		
		- Haran	/Under Maintenance			
Work is	The reserve to the state of the	3	p gradation/ Maintenance	No.		A.
SI. No.	是有一种。 14	Parameters to	be checked	- 5- 1-1	Remarks	
1.	Pavement					
a)	Road Junction condition				S/U	
b)	Condition of Surfacing (warm in posts)				_S/H	
c)	Riding Quality				S/10	
d)	Road Camber				<i>S</i> 1Ú	
e)	Whether free from defects such as visible cracks, expending aggregates in case of CC Pavement.				Yes/No	
ſ)	Contraction Joints provided or not (CC Pavement)				Yes/No	
g)	Compaction of flank/slope & raincuts if any				Yes/No	
2	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its pair				S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U	
c)	Condition of railings/slab/approach for Bridges				S/SRI/U	
3.	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 20 stones/Pavement road markings are provided and maintained				Yes/No	
4.7	Compliance History				10 10 10 cm	
a)	Status of ATR's					
Overall I		Satisfactory (S)		CDT	_ح_	
			requires Improvement (	SRI)		
		Unsatisfactory (U	J)			
~						
			¥		1 man	>
					nature)	
				(Sig	nature	
PAMOIE	TICHAY PARM					1

NAME:

Scanned by CamScanner