## FIELD INSPECTION REPORT

Date of	Inenaction	T. T	all of the town	
Date of Inspection: 03 10 1.00			District: Bhagalour Length (km): 1-15 Key	
Division: Kahalgaan Leny Name of the Road: RD path Amarbur				
Scheme	Programme:	MAINTENANCE AS	en Mainterance	policy.
Package	e No.:	Ro	nd Id No.:	1 0
Status of the Project: Ongoing/Completed			of Municipality	ng between
Work is	a case of:	New Connectivity/Up gra	ndation/ Maintenance	
Sl. No.		Parameters to be c	hecked	Romarks
L	Pavement	A CONTRACTOR OF THE PARTY OF TH	The state of the	
a)	Road Junction condition			_S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			_S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No .
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b)				S/SRI/U
c)	Condition of railings/slab/approach for Bridges S/SRI/U			S/SRI/U
-3.	Road Furniture			
a)	The state of the s			Yes/No
4.	Compliance History			The state of
a)	Status of ATR's & any others		No	
	Cartes and the second		is in tonder	mocess.
Overall Rating :		Satisfactory (S)		/
		Satisfactory but requi	res Improvement (SRI)	25A
		Ungatisfactory (II)		1

Unsatisfactory (U)

(Signature)

NAME:

Scanned by CamScanner