

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020	District: Jamui
Division: Jamui	Length (km): 4.127
Name of the Road: Mangobandar to Chanchun Katari	
Scheme/Programme: MAINTENANCE	
Package No.: MR-W/19-20 Jamui/15	Road Id No.: 28411032567
Status of the Project: Ongoing ☒ Completed ☐ Under Maintenance ☐	
Work is a case of: New Connectivity ☐ Up gradation ☒ Maintenance ☒	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Rating Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes ☒ No ☐
f)	Contraction Joints provided or not (CC Pavement)	Yes ☒ No ☐
g)	Compaction of Bank slope & raincuts if any	Yes ☒ No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓/SRI/U
c)	Condition of railings/slab approach for Bridges	✓/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes ☒ No ☐
4.	Compliance History	N/A
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

NAME:

for
2/12/2020
J.E

for
02/12/20
A.O

(Signature)