FIELD INSPECTION REPORT

Date o	finspection: 03/12/2020	District: James	
Division: James		Length (km): 2.30 Km.	
	of the Road: Baskof PWD R	ead to Bhaluko	4
_	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Road Id No.: 28411037	402
	of the Project: Ongoing/Completed/		2002
Work		gradation/ Maintenance	
Sl. No.	Parameters to b	e checked	Remarks
1	Payement		A Thomas and
a)	Road Junction condition		SAU
b)	Condition of Surfacing		SAU
c)	Riding Quality		S/U
d)	Road Camber :		S/U
e)	Whether free from defects such aggregates in case of CC Pavement.	as visible cracks, exposed	Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Xcs/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe	TOTAL PROPERTY AND ADDRESS AND	S/SRH/U
b)	Condition of Abutment & Wing walls,	Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for	Bridges	S/SRI/U
	Road Furniture	Accept to the	
a) 🕏	Whether sign boards/informatory/cau stones/Pavement road markings are pro	vided and maintained	Yes/No-
		positive and the second	
a)	Status of ATR's & any others		NIA

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	F B 1
Unsatisfactory (U)	

NAME:

CALOR Vines Aye

AE, RND, Laxupus

(Signature)