

FIELD INSPECTION REPORT

Date of Inspection : 4-12-2020	District: Darbhanga
Division : Darbhanga-1	Length (km): 0.825 KM
Name of the Road: Kabilpur village to chatti chowk	
Scheme/Programme: MAINTENANCE	ongoing.
Package No.: New Maintenance Policy	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A S/U
b)	Condition of Surfacing	N/A S/U Ongoing
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A ongoing
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO.

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Vinay Kumar

DESIGNATION: A.E. Bahadurpur.

(Signature) 4/12/2020