

New maintenance policy
In process of Revised A.A

Block: - pimpanti

NA

FIELD INSPECTION REPORT

Date of Inspection: 03/10/2020	District: Bhagalpur
Division: Mahaganj	Length (km): 15 km
Name of the Road: pimpanti to Bakhaspur via Badi Madhusaon	
Scheme/Programme: MAINTENANCE	<u>New maintenance policy</u>
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Ongoing
Work is a case of: New Connectivity/Up gradation/ Maintenance	Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Speed Limit History	
a)	Status of A.R.s & any issues	No

Overall Rating :

Road is in process of Revised A.A

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	

On 03/10/2020
(Signature)
RG

NAME: