(Brock - oran

FIELD INSPECTION REPORT

| | | | 1 |
|--|---|-----------|------|
| Date of | Inspection: 03 12 2020 District : Bhagalpur | | |
| Division Bhagalpur Length (Km): 6 . Swo V | | m | |
| Name o | f the Road: SH-85 Rivanbur to Racula | Rath. | |
| Scheme | / Programme : MAINTENANCE | | |
| Package | No. / Group No 14 Road Id No.: 2>32103 | 2925 | |
| and the second second | the Project: Ongoing / Completed / Under Maintenance | | |
| Work is | a case of: New Connectivity / Up gradation / Maintenance | | |
| SL. No. | Parameters to be checked | Remarks | |
| 1. | Pavement | | |
| a) | Road Junction condition | SHU) | |
| b) | Condition of Surfacing | \$.AU (| |
| c) | Riding Quality | StU N | A |
| d) | Road Camber | S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No) | |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No(n | 44 |
| g) | Cpmpaction of flank/slope & raincuts if any | Yes/No | 1 0 |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U | |
| b) | Condition of Abutment & Wing Walls, Slab in RCC culverts | S/SRI/U | ~! N |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U | 1414 |
| 3. | Road Furniture | | |
| a) | Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained. | Yes / No | |
| AND PROPERTY OF THE PARTY OF TH | Compliance History | | |
| a) S | Status of ATR's & any others | | |
| erall Rati | ing: Work has been hot been Stanted | NO | |
| : | Satisfactory (S) | yet. | |
| : | Satisfactory but requires Improvement (SRI) | | |
| | Unsatisfactory (U) | ALI | |
| | | | |

NAME: Meeras Kumar

DESIGNATION: J.E

(Signature)