FIELD INSPECTION REPORT

Name of Road:		Laper chorak la pinulea via Kalta	0	
		12 2 4 11000 K to 01001200 VIO (0110)	4	
Scheme/ Programme:		MAINTENANCE		
Packago	05-10/11-4M.on	Road ID No. 211551033028		
Status of the Project:		Onging/Completed/Under Maintenance		
Work is	a case of:	New Connectivity/ Up Gradation/ Maintenance	mais P	
SLNo		Parameters to be Checked	Remarks	
1	Pavement,	The state of the s	A STATE OF THE PARTY OF THE PAR	
a)	Road Junction Con	dition	s/U N	
b)	Condition of Surfa	cing	S/U	
c)	Riding Quality	. T. T.	S/U (
d)	Road Camber		s/U N	
e)	Whether free from CC Pavement	defects such as visible cracks, exposed aggregates in case of	Yes/No	
f)	Contraction Joints J	provided or not (CC Pavement)	Yes/No \	
g)	Compaction of flan	k/slpoe & raincuts if any	Yes/No	
2	Cross Drainage			
a)	Condition of headw	alls inn Humepipe culverts including its painting	S/SRI/U	
b)	Condition of Abutn	nent & Wings walls, Slab in RCC culverts	S/SRI/U	
c) (Condition of railings/slabs//approach for Bridges		S/SRI/U	
3]	Road Furniture			
1	Whether sign board oad markings are p	s/informatory/cautionary Board/Km & 200m stone/ Pavement rovided and maintained.	LYes/No	
	Compliance Histor			
a) Status of ATR & any		y others	No	
			0	
verall Grading:		Satisfactory (S)	-	
		Satisfactory but requires Improvement(SRI)		
		Unsatisfactory (U)		
			Ω	
^	- 1	$\alpha \ell \nu$	M	
me: 🗥	2 Kilosidon	(Signature Copinson	re)	
gisnation	n Diani		(e) N 5	
J	Las 11 of	(2) 21250		
		7		