FIELD INSPECTION REPORT

Date of Inspection: 03/11/2020			District: Malanda		
Division: Bihar shart		und Len	Length (km): 2.575 Km		
Name of	the Road: 14 H	31 to patasang to Am	ba		
Scheme/Programme: MAINTENANCE			New maintenance policy - 2018		
Package No.:			Road Id No.:		
Status of the Project: Work is a case of:		Ongering/Completed/Under Maintenance			
	a case of:	New Connectivity/Up gra			
Sl. No.		Parameters to be checked		Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
n	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.,;	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRL/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/L	
c)	Condition of railings/slab/approach for Bridges			S/SRI/L	

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Overall Rating

3.

a)

4.

a)

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Yes/No

Hil

Road Furniture

Compliance History

Status of ATR's & any others

NAME: AJeefkumarsingle DESIGNATION: Junier engg.

Scanned with CamScanner