FIELD INSPECTION REPORT SIECE SWITCH SWITCH

ate of Ir	(Sultanga) Bhogalho Length (Km): 2.250 km.	
vision:	(Sultengai) Bhogalhy Length (Km): 2.250 to.	
ame of	the Road: Nonsar manghi Tola Chusic to Rampur Na H	avin Jola Panchyo
cheme/	Programme: MAINTENANCE	
	No.: Group No-11 Road Id No.: 27321033245.	
	the Project: Ongoing /completed/Under Maintenance	
	a case of : New Connectivity/Up gradation/ Maintenance	Remarks
L. No.	Parameters to be checked	Remarks
1	Pavement	120
a)	Road Junction condition	G/S/U
b)	Condition of Surfacing	s/U
c)	Riding Quality	s/u
d)	Road Camber HK	s/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Cpmpaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	L.M
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/L
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 stones/Pavement road markings are provided and maintained	m Yes/N
144	Compliance History	M
la l	Status of ATR's & any others	

Overall Rating:

Satisfactory(S)	SRI	
Satisfactory but requires Improvement (SRI)	1-1	
Unsatisfactory(U)	W. JAH	ļ

NAME: H.N. makto.

DESIGNATION: E.E. Bhoyalbw.