

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020	District: Bhagalpur	
Division: Bhagalpur	Length (Km): 1.50 km	
Name of the Road: Belahira to Harichampur via prampur		
Scheme/Programme: MAINTENANCE		
Package No.: Group - 52	Road Id No.: 273210322A9	
Status of the Project: Ongoing /completed/Under Maintenance		
Work is a case of : New Connectivity/Up gradation/ Maintenance		
SL. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NA Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

NA

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

Note. Work has not been started.

NAME:

DESIGNATION:

Signature
02/12/2020
J.E.
Nathnagar

(Signature)

Signature
03/12/2020
(31011 31011 31011)
4841 840001,
011410012