

FIELD INSPECTION REPORT

Block - Sultangarj

Date of Inspection: 3.12.20 District: Bhagalpur.		
Division: (Sultangarj) Bhagalpur Length (Km): 0.340		
Name of the Road: NH-80 Maheshi Railway Station Tail.		
Scheme/Programme: MAINTENANCE		
Package No.: Group No. 11 Road Id No.: 27321033250		
Status of the Project: Ongoing / completed / Under Maintenance		
Work is a case of : New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	HA S/U
b)	Condition of Surfacing	HA S/U
c)	Riding Quality	HA S/U
d)	Road Camber	HA S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	HA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	HA Yes/No
g)	Cmpaction of flank/slope & raincuts if any	HA Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	HA S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	HA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	HA S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

work in progress. E/W is going on.

Satisfactory(S)	✓
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	✓

(Signature)

NAME: H.N. Mahato.

DESIGNATION: E.E. Bhagalpur.