

FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	Nalanda
Division :	Delhi	Length (km):	1.55
Name of the Road:	Dhaka Ghod to Kalkua		
Scheme/Programme:	MAINTENANCE		
Package No.:	RM/NA/RAJ/20/004	Road Id No.:	129/033630
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No No	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

S. S. S.
3/12/2020
(Signature)

NAME: Shiva Prakash Guleri

DESIGNATION: A. E.

Scanned with CamScanner

Scanned with CamScanner