

FIELD INSPECTION REPORT

Block:- pirpanth

Date of Inspection :	03/12/2020	District:	Bhogalpur
Division :	Kabulgaon	Length (km):	3.0 km
Name of the Road:	NH-80 Sadhu Mathia to Bansi chote		
Scheme/Programmet:	MAINTENANCE	New maintenance policy	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <u>ongoing</u>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>Maintenance</u>		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<u>S/U</u> NA
b)	Condition of Surfacing	<u>S/U</u> NA
c)	Riding Quality	<u>S/U</u> NA
d)	Road Camber	<u>S/U</u> NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<u>Yes/No</u> NA
f)	Contraction Joints provided or not (CC Pavement)	<u>Yes/No</u> NA
g)	Compaction of flank/slope & raincuts if any	<u>Yes/No</u> NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<u>S/SRI/U</u> NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<u>S/SRI/U</u> NA
c)	Condition of railings/slab/approach for Bridges	<u>S/SRI/U</u> NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<u>Yes/No</u> NA
4.	Compliance History	
a)	Status of ATR's & any others	<u>No</u>

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	<u>NA</u>

work not start

(Signature)
At

NAME: