FIELD INSPECTION REPORT

Date o	of Inspection: 4 12	12020 District: Koh'hor	
Name of Road:		Bori Bhow'ng Dirochowk to fokir plo	
Schem	ie/ Programme:	MAINTENANCE	
Packa	ge No. MA-N/19-20	40 h now No. 211551034595	
Status of the Project:		Onging/Completed/Under Maintenance	
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
SLNo	No. of Personal Control of the Contr	Parameters to be Checked	Company of the second second second
1	Pavement	an america to be Checked	Remarks
a)	Road Junction Con	dition	s/U N
b)	Condition of Surfacing S/U		
c)	Diding Overlie		S/U N
d)	Road Camber		S/U (V
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No (
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)			Yes/No
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting		S/SRI/U(
b)			S/SRI/U
c)	Condition of railings/slabs//approach for Bridges S/SRI/U		S/SRI/U
3,	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		/ Yes/No
4	Compliance Histor		
a)	Status of ATR & an	y others	
verall Grading:		Satisfactory (S)	S
		Satisfactory but requires Improvement(SRI)	4
		Unsatisfactory (U)	1

Name: Montanto Trainer

Scanned by CamScanner