## FIELD INSPECTION REPORT

Date of It	Ispection: 02/12/2020 District: Nalande		
Name of	the Dar Shorik Length (km): 0,640 km		
octiom ()	11765[81 1101 10 37]		
WAEC	No. and		
Status of	the Project: Ongwing/Completed/Under Maintenance	ork into	njoss)
Work is	the Project: Ongwing/Completed/Under Maintenance		
Sl. No.			
	Parameters to be checked	Remarks	
1.	Pavement		
a)	Rond Junction condition	S/U	7
b)	Condition of Surfacing	S/U	w)
c)	Riding Quality	S/U	
d)	Road Camber	S/U	1 (
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	24
g)	Compaction of flank/slope & raincuts if any	Yes/No	] 15W
2.	Cross Drainage		Not
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	900
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
<b>a</b> )	Whether sign boards/informatory/cautionary Board/km & 200r stones/Pavement road markings are provided and maintained	Yes/No	
24.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	-3	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

Signature

NAME: Mojib -Ahmad

DESIGNATION: J.E.

Scanned with CamScanner

Scanned with CamScanner