FIELD INSPECTION REPORT

ate of	Inspe	ection: 93	112/20		District: Natoredo	
hilata Dil ida					Length (km): 2-20 KAO	
ame	of the	Road: NA	1-317	o Bixab	ali hate her Bidhi Ha	spital
Schem	e/Pro	ogramme:	MAINT	ENANCE	New Mainference Police	y 2018
Packa	ge No	n.:			Ruau lu ivo.	
-		he Project:			Under Maintenance	
Work is a case of: New Connectiv				onnectivity/	Up gradation/ Maintenance	Remarks
SI. No.			P	Parameters to be checked		
1.	. 1	Pavement			,	
(a		Road Junction condition				S/U
(b)		Condition of Surfacing				S/U
-	c)	Riding Quality				S/U
-	<u>d)</u>	Road Camber				S/U
+	e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
+	n	Contraction Joints provided or not (CC Pavement)				Yes/No
+	g)	Compaction of flank/slope & raincuts if any				Yes/No
+	2.					
t	a)	Gardition of head walls in Huma nine sulverts including its painting				S/SRI/U
b)		G. Liting of Abutment & Wing wells Clab in DCC gulyants				S/SRI/U
		Condition of railings/slab/approach for Bridges				S/SRI/U
	1111	Road Furniture				
		Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/No
	75	4. Compliance History				
	F	a) Status of ATR's & any others				
	Overall Rating			Satisfactory	(S)	-
			but requires Improvement (SRI)	S		
				Unsatisfact	ory (U)	

(Signature)

NAME: Arrid vener DESIGNATION: JULION FLYINGEY

ZA