## FIELD INSPECTION REPORT

Date of Inspection: 03/12/20			District: Nalenda		
Division: Bikarshary			Length (km): 0-657 KM		
iame of	the Road: Bil	ar Ekangar Roa	d (Golapox) to Airport		
cheme/l	'rogramme:	MAINTENANCE	New maintenance Policy	2018	
Package No.:			Road Id No.:		
			/Under Maintenance		
	a case of:		Jp gradation/ Maintepance		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  Yes/No			Yes/No	
ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges				
3	Road Furniture S/SRI/U				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/No				
4.30	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	5
Unsatisfactory (U)	

NAME: Arvind Kungr

DESIGNATION: J. C

, ,

(Signature)