

FIELD INSPECTION REPORT

Date of Inspection : 04/12/20		District: Bgmk	
Division : Bgmk-1		Length (km):	
Name of the Road: Amarpur Sahkund road to Doung			
Scheme/Programme: MAINTENANCE			
Package No.: RM/BA/BAN/20/0002		Road Id No.: 27351036033	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	ongoing
b)	Condition of Surfacing	S/U	ongoing
c)	Riding Quality	S/U	ongoing
d)	Road Camber	S/U	ongoing
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	ongoing
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	ongoing
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	ongoing
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NO
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Dkumar
 04/12/2020
 (Signature)

NAME: DHARMVEER KUMAR

DESIGNATION: J.E.