FIELD INSPECTION REPORT

Date of Inspection :	04/12/200	District: Helanda		
Date of Inspection: 04/12/2020 Division: Bihar Stant		Length (km): 0.570		
Name of the Road:	Ol Pol ul factor	no secret to Uprouls	0.419	
Scheme/Programm	: MAINTENANCE	Now maintenance pull	14-1010	
Package No.:		Road Id No.:	1 2 /544	
Status of the Project: Ongoing/Comple			ter policy	
Work is a case of:	New Connectivity/	New Connectivity/Up gradation/ Maintenance		
SI. No.	Parameters to	be checked	Remarks	

SI. Na.	Parameters to be checked	Remarks
1,	Pavement	part to
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
ŋ	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRL/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	
a)	Status of ATR's & any others	Hil

Overall Rating

Satisfactory (S)	17
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

BE 04/12/2020

MA

(Signature)

NAME: Brinad Kumar Singh

DESIGNATION: J. 区

Scanned with CamScanner