


FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020		District: Banka
Division : Banka-2		Length (km): 1.710
Name of the Road: Bulundi Rampurpasa to Kharao		
Scheme/Programme: MAINTENANCE		
Package No.: RM/BA/BAN/20/0003		Road Id No.: 20703502069
Status of the Project: ☒ Ongoing/Completed/Under Maintenance		
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No on-going
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U on-going
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No on-going
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S 'Satisfactory'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


02/12/20
(Signature)

NAME: RAMESH KUMAR

DESIGNATION: JE