FIELD INSPECTION REPORT

Date of Inspection: 02.12.2020			District: Banka		
Division: Bankg-2			Length (km): 12-74 KM		
	f the Road:	hyeur - Berzar - 19	Sherjir Dam Road	A DOMESTIC STATE	
	Programme:	MAINTENANCE		. 0	
Status o	f the Project:	BAN/19/0003	Road Id No.: 2070 350 21 2	2	
	a case of:	The state of the s	/Under Maintenance Ip gradation/ Maintenance	Skilling Co.	
Sl. No.	15419644 Changers and a combination		CONTRACTOR DE LA CONTRA	Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainag	gerijiiiiii			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance H	istory		The state of the s	
a)	Status of ATR's	s & any others	A STATE OF THE STA		

Overall Rating

Satisfactory (S)	S	Sats factory
Satisfactory but requires Improvement (SRI)	-	
Unsatisfactory (U)		

 $\begin{array}{c} \frac{\rho_{r'}(1-w)}{0.21\cdot(12\cdot10)}\\ \text{(Signature)} \end{array}$

NAME: PRITAM KUMAR

DESIGNATION: KE