

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		District: Banka	
Division : Banka-1		Length (km): 1.5	
Name of the Road: Deoda Main Rd to Bghera			
Scheme/Programme:		MAINTENANCE	
Package No.: RM/BA/BAN/19/0002		Road Id No.: 20703502232	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No	N.A ongoing.
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	Ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N.A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Ongoing.
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	Satisfactory (S).
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Pritham
02.12.2020
(Signature)

NAME: PRITHAM KOMAR

DESIGNATION: A.E