FIELD INSPECTION REPORT

Date of I	nspection :	Dist	rict: BANKA	
Division: Banka=1		Leng	Length (km): 3.50	
		hapri More to si	rihari	
Scheme/	Programme:	MAINTENANCE		
Package			d Id No.: 20703502	.233
	the Project:	Ongoing/Completed/Unde	A STATE OF THE PARTY OF THE PAR	
Work is	a case of:	New Connectivity/Up grad	lation/ Maintenance	to the control of the state of
Sl. No.		Parameters to be ch	ecked	Remarks
i.	Pavement		The state of the s	
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			√ ś/ U
c)	Riding Quality			√s/U
d)	Road Camber			√s/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Xes/No
2.	Cross Drain	ige		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U S/SRI/U S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			was Maria
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance	History		
a)	Status of AT	R's & any others		
	*			-

Overall Rating :

Satisfactory (S)	satisfactory	(()
Satisfactory but requires Improvement (SRI)	Listration	(3
Unsatisfactory (U)		

Official (Signature)

NAME: Dharmveer Kumon

DESIGNATION: JE