

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	District: Munger
Division : Munger	Length (km): 2.330
Name of the Road: To 1 - Myagachon to Mahuli	
Scheme/Programme: MAINTENANCE	MR - New
Package No.:	Road Id No.: 1636
Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance	
Work is a case of: New Connectivity / Up gradation / Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others - Road Furniture on the road is ✓	✓

Overall Rating :

Satisfactory (S)	✓S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ravi Shankar Mandal
J.E.

NAME:

Mandal
03.12.2020
(Signature)