

# FIELD INSPECTION REPORT

| Date of Inspection :    | 4-12-2020                                                                                                                         | District :                                  | Mungel       |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|--------------|
| Division :              | Kharapur - Tarapur                                                                                                                | Length (Km) :                               | 2.5 Km       |
| Name of the Road :      | Mahapur to Sishua road                                                                                                            |                                             |              |
| Scheme/Programme :      | MAINTENANCE / NMP 2018                                                                                                            |                                             |              |
| Package No. :           |                                                                                                                                   | Road Id No. :                               | SL No : - 37 |
| Status of the Project : | <input checked="" type="checkbox"/> Ongoing/ <input type="checkbox"/> Completed/ <input type="checkbox"/> Under Maintenance       |                                             |              |
| Work is a case of :     | <input type="checkbox"/> New Connectivity/ <input type="checkbox"/> Up gradation/ <input checked="" type="checkbox"/> Maintenance |                                             |              |
| Sl. No.                 | Parameters to be checked                                                                                                          | Remarks                                     |              |
| 1                       | <b>Pavement</b>                                                                                                                   |                                             |              |
| a)                      | Road Junction condition                                                                                                           | <input checked="" type="checkbox"/> S/U     |              |
| b)                      | Condition of Surfacing                                                                                                            | <input checked="" type="checkbox"/> S/U     |              |
| c)                      | Riding Quality                                                                                                                    | <input checked="" type="checkbox"/> S/U     |              |
| d)                      | Road Camber                                                                                                                       | <input checked="" type="checkbox"/> S/U     |              |
| e)                      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                                      | <input checked="" type="checkbox"/> Yes/No  |              |
| f)                      | Contraction Joints provided or not (CC Pavement)                                                                                  | <input checked="" type="checkbox"/> Yes/No  |              |
| g)                      | Compaction of flank/slope & raincuts if any                                                                                       | <input checked="" type="checkbox"/> Yes/No  |              |
| 2                       | <b>Cross Drainage</b>                                                                                                             |                                             |              |
| a)                      | Condition of head walls in Hume pipe culverts including its painting                                                              | <input checked="" type="checkbox"/> S/SRI/U | } N/A        |
| b)                      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                                          | S/SRI/U                                     |              |
| c)                      | Condition of railings/slab/approach for Bridges                                                                                   | S/SRI/U                                     |              |
| 3                       | <b>Road Furniture</b>                                                                                                             |                                             |              |
| a)                      | Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained              | <input checked="" type="checkbox"/> Yes/No  |              |
| 4                       | <b>Compliance History</b>                                                                                                         |                                             |              |
| a)                      | Status of ATR's & any others                                                                                                      | N o                                         |              |

Overall Rating :

|                                                      |  |
|------------------------------------------------------|--|
| Satisfactory (S) <input checked="" type="checkbox"/> |  |
| Satisfactory but requires Improvement (SRI)          |  |
| Unsatisfactory (U)                                   |  |

NAME : Suresh Kumar  
DESIGNATION : A/E

S. K. K.   
04.12.2020  
(Signature)