

FIELD INSPECTION REPORT

Date of Inspection :	03-12-2020	District :	MUNGER
Division :	KARAIK PUR - TARA PUR	Length (Km) :	3.0 KM
Name of the Road :	R.D. GANGTA SANGRAM PUR ROAD TO NAGATI VIA DEOGHARA		
Scheme/Programme :	MAINTENANCE NEW MAINTENANCE POLICY		
Package No. :		Road Id No. :	SL No 47
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	IN PROGRESS.
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NOW WORK
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NOW
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	{	NOW
Satisfactory but requires Improvement (SRI)		N.A
Unsatisfactory (U)		

LOK PRASAD RAY

Q