## FIELD INSPECTION REPURI

Date of Inspection:	District: PATNA	
Division: DANAPUR	Length (km): 1.050	
lame of the Road: Bil	nta saiwala path to soichandpur.	
1 (Programme)	MAINTENANCE	
No. NO. 10	1-20-Dana Pus 07 Road Id No.:	
tatus of the Project:	Opening/Completed/Under Wantenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	Remarks
SI. No.	Parameters to be checked	And Lay Copies And Annal S
1. Pavement	the second se	S/J
a) Road Junction	Road Junction condition	
	Condition of Surfacing	
	Riding Quality	
- 10 1	Road Camber	
<u> </u>	Whether free from defects such as visible cracks, exposed	
e) whether free	aggregates in case of CC Pavement.	
	Contraction Joints provided or not (CC Pavement)	
·	Compaction of flank/slope & raincuts if any Work in Progress.	
2. Cross Drain	THE PROPERTY OF THE PROPERTY O	
	head walls in Hume pipe culverts including its painting	S/SRI/U 7
	Condition of Abutment & Wing walls, Slab in RCC culverts	
	Condition of railings/slab/approach for Bridges	
The state of the s		
3. Road Furni	2	
a) Whether sig	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4. Compliance	History	
a) Status of AT	TR's & any others	
Overall Rating	: Satisfactory (S)	S
	Satisfactory but requires Improvement (SRI)	7
	Unsatisfactory (U)	

3/12/2020 J.E. Bilda

(Romesh Kumar Singh)

(Signature)

NAME:

DESIGNATION: