

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District : - SAHARSHA
Division : SIMRIBAKTIYARPUR	Length (km): 1.50 km.
Name of the Road: DUMRA TO BALTORAGHAT TRIYAMA VIA LAGMA.	
Scheme/Programme: MAINTENANCE - 3054	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	- ongoing
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N.A
b)	Condition of Surfacing	S/U N.A
c)	Riding Quality	S/U N.A
d)	Road Camber	S/U N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No N.A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N.A C.I. Fizer board only.
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

work not started.

NAME:

02/12/2020
A.E.

(Signature)

Executive Engineer,
Works Division,
Simrribaktiarpur