

FIELD INSPECTION REPORT

Date of Inspection : - 2/12/2020	District: SAHARSHA
Division : SIMRI BAKHTIYARPUR	Length (km): - 1.54 K.M.
Name of the Road: DUMRA TO LAGMAPATTI	
Scheme/Programme: MAINTENANCE - 3054	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	- Ongoing
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N.A
b)	Condition of Surfacing	S/U N.A
c)	Riding Quality	S/U N.A
d)	Road Camber	S/U N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No N.A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Citizen Board Yes/No Only.
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

work not started.

NAME:

[Signature]
A.E.

[Signature]
Executive Engineer,
R.W.D. Works Division,
Simri Bakhtiyarpur