

FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020	District: Khagaria
Division : Gogri	Length (km): 1.830 km
Name of the Road: Mali to Bhishanpur	
Scheme/Programme: MAINTENANCE / M2-3054	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	In Progress
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	'S' S/U
b)	Condition of Surfacing	'S' S/U
c)	Riding Quality	'S' S/U
d)	Road Camber	'S' S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No In Progress
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	- S -
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NAME: Kulnand yadav

[Signature]
02/12/20

[Signature]
02.12.20
(Signature)