


FIELD INSPECTION REPORT

Date of Inspection :- 3.12.20		District :- Khasani	
Division :- Khasani		Length (Km) :- 6.00	
Name of Road :- Parmanandpur Phala Khasani se Mansi Tak Path			
Scheme/Programme :- MR old		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :- completed		Ongoing/Complete/Under Maintenance ☒	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S S/U
b)	Condition of Surface	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No Yes/No
f)	Construction Joints provided or not (CC Pavement)	Yes Yes/No
g)	Compaction of flank/slope & raincuts if any	No, Yes Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b) -	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/ Pavement road markings are provided and maintained	Yes Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S) ☒	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 3.12.20
 (Signature)
 J.E. Mansi