## FIELD INSPECTION REPORT

	spection: D	4112/2020	District: Khajana		
908YL			Length (km): 1, CC		
and the same of th	The second of th	Dighaun D	ih to Pachauth 1	uore	
	ingramme;	MÄINTENANCE	MR-3054	and the same of th	
ackage	The state of the s		Road Id No.:		
			ompleted/Under Maintenance On going		
Sl. No.		New Connectivity/	New Connectivity/Up gradation/ Maintenance		
		Parameters t	o be checked	Remarks	
1.	Pavement				
a)	Road Junction condition			S/U (	
b)	Condition of Surfacing			S/U \	
c)	Riding Quality			S/U <	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g) .	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U(	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance				
a)	Status of ATR's & any others			No	

Overall Rating

Satisfactory (S)	51
Satisfactory but requires Improvement (SRI)	and the same and in concentration to the same and the sam
Unsatisfactory (U)	

NAME:

Ramesh Kr Salva

**DESIGNATION:**