FIELD INSPECTION REPORT

Date of Inspection: 03.12.2020 Division: Gagni			District: Khaggrig Length (km): 2.5 km.	
Scatemer	i rogramme:	MAINTENANCE	MR 3054	
Package	The State of		Road Id No.: 20904608	156
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance		
The second second	a case or:	State and Alliance interpretation	/Up gradation/ Maintenance	2.00
Sl. No.		Parameters t	o be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/0
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether freaggregates in	Yes/No7		
f)	Contraction Joints provided or not (CC Pavement)			Yes/No M
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Gross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U \
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
, c)	Condition of railings/slab/approach for Bridges			S/SRI/U (
3.	Road Furnit	ure		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

03:12:2020 J.E

Compliance History

Status of ATR's & any others

Atuma 3117/2120

Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained

(Signature)

Yes/No

NAME:

DESIGNATION: