


FIELD INSPECTION REPORT

Date of Inspection : 03/12/20		District: Madhe pargana	
Division : Uda Kishkurgan		Length (km): 3.40 km	
Name of the Road: Pipra Kishkurgan to Uda Kishkurgan			
Scheme/Programme: MAINTENANCE		Road Id No.: 2104202091	
Package No.:		MDTAWATP (D)	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U MA	
a)	Road Junction condition	S/U MA	
b)	Condition of Surfacing	S/U MA	
c)	Riding Quality	S/U MA	
d)	Road Camber	Yes/No MA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No MA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No MA	
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage	S/SRI/U MA	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U MA	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U MA	
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture	Yes/No MA	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	MAINTAINED
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 03/12/20
 (Signature)
 JE Uda Kishkurgan

NAME:
 PANKAJ KUMAR