


FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020		District: Patna
Division : Masaurhi		Length (km): 3.600 km
Name of the Road: Repair of Road Thubha to Dubhara		
Scheme/Programme: MAINTENANCE		✓
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance ✓
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	U S/U
b)	Condition of Surfacing	U S/U
c)	Riding Quality	U S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	No Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U


 2/12/2020
 (Signature)

NAME: Pushkar Prasad
 DESIGNATION: Assistant Engineer