

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Purnea
Division : BAISI	Length (km): 2.260 km
Name of the Road: Ashiyani Idgan Chowk to Lakhanse Jammaa Road	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	☒ Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U-NA
b)	Condition of Surfacing	S/U-NA
c)	Riding Quality	S/U-NA
d)	Road Camber	✓ S/U-NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No-NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No-NA
g)	Compaction of flank/slope & raincuts if any	Yes/No-NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U-NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U-NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U-NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	NA (Recently work has been started)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Prasanna Kumar
(Signature) 03/12/2020

NAME: GIAURAV KUMAR
DESIGNATION: ASSISTANT ENGINEER