	FIELD INSPECTION REPORT		
DATE OF INSPECTION:	64/22/2020 DISTRICT: PURNEA		
DIVISION:	Dhandorn. LENGTH: 4.920 for		
NAME OF THE ROAD:	Ramper parisar To Dongan inte Dilla Tola.		
SCHEME/PROGRAMME:	MAINTENANCE Pg. 920 km		
PACKAGE No:	ROAD ID No.: 2-1105301024		
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SLNO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	<b>ル・</b> な	
8	CONDITION FO SURFACING	N· A	
С	RIDING QUALITY	NA	
D	ROAD CAMBER	N-A	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	N·A	
ř.	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N· A	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	N· A	
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N.A	
В .	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N^ A N∙ A	
С	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N. A	
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	5	
4	COMPLIANCE HISTORY		
Α	STATUS OF ATR''S & ANY OTHERS	NO ANY ATR	
VERALL RATING			

OVERALL RATING

	-
SATISFACTORY(S)	5
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	_
UNSATISFACTORY(U)	

NAME: Kamal Naryan sharma. DESIGNATION: Junior Eorgineer

Scanned by CamScanner