|                                 | FIELD INSPECTION REPORT  |                      |
|---------------------------------|--|----------------------|
| DATE OF INSPECTION:             | 04/10/2020 DISTRICT: PUR.  | NEA                  |
| DIVISION:                       | DHAMDAHA LENGTH: 6.650 KM  |                      |
| NAME OF THE ROAD:               | 04/12/2020 DISTRICT: PURNEA  DHAMDAHA LENGTH: 6.650 km  Ashokopa To Laxmifur (Chharapa Hi)                     |                      |
| CHEME/PROGRAMME:                | MAINTENANCE  |                      |
| PACKAGE No:                     | ROAD ID No.: 21105302003   |                      |
| TATUS OF THE PROJECT:           | ONGOING/COMPLETED/UNDER MAINTENANCE  |                      |
| WORK IS A CASE OF:              | NEW CONNECTIVITY/UP GRADATION/MAINTENANCE  |                      |
| SLNO                            | PARAMETERS TO BE CHECKED   | REMARKS              |
| 1                               | PAVEMENT   |                      |
| Α                               | ROAD JUNCTION CONDITION  | an . u               |
|                                 | CONDITION FO SURFACING   | µ· A                 |
| В                               |  | N· D                 |
| С                               | RIDING QUALITY   | N- V                 |
| D                               | WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED  | W. V.                |
| E                               | AGGREGATES IN CASE FO CC PAVEMENT  | N- 19                |
| F                               | CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)  | N.A                  |
| G                               | COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY  |                      |
| 2                               | CROSS DRAINAGE  CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS  N. A.                             |                      |
| А                               | PAINTING   | N·A.                 |
| В                               | CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS   | N·A                  |
| С                               | CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES   | N· A                 |
| 3                               | ROAD FURNITURE   |                      |
| Λ                               | WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M<br>STONES/PAVEMENT ROAD NARKING ARE PROVIDED AND MAINTAINED | 8                    |
| 4                               | COMPLIANCE HISTORY   |                      |
| Α                               | STATUS OF ATR"S & ANY OTHERS   | No Any ATR.          |
| VERALL RATING                   | ,  |                      |
| V ENVICE IN THE                 | SATISFACTORY(S)  | <u>- 3</u>           |
|                                 | SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)   | <del>-</del> · · · · |
| 4-                              | Revised DPR submitted to CE-4  |                      |
|                                 | Mensed Direct  | 18/12/20             |
|                                 | an sharma.   | SIGNATURE            |
| : KAMH NATY<br>NATION: JYNIOT E | Engineer   | SIGNATURE            |