

FIELD INSPECTION REPORT

DATE OF INSPECTION:	04/12/2020.	DISTRICT:	PURNIA
DIVISION:	Dhamdaha.	LENGTH:	3.60km
NAME OF THE ROAD:	Kamp (Konkola) - Bharoria via Buiranga.		
SCHEME/PROGRAMME:	MAINTENANCE		
PACKAGE No:	ROAD ID No.: 21105302037		
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SLNO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	N.A	
B	CONDITION OF SURFACING	N.A	
C	RIDING QUALITY	N.A	
D	ROAD CAMBER	N.A	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT	N.A	
F	CONTRACTION JOINTS PROVIDED OR NOT (CC PAVEMENT)	N.A	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	N.A	
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N.A	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N.A	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A	
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	S	
4	COMPLIANCE HISTORY		
A	STATUS OF ATR's & ANY OTHERS	No Any ATR	

OVERALL RATING

SATISFACTORY(S)	S
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	—
UNSATISFACTORY(U)	—

NAME: Kamal Narayan Sharma.
DESIGNATION: Junior Engineer

[Signature]
4/12/2020
SIGNATURE