	FIELD INSPECTION REPORT	
DATE OF INSPECTION:		
DIVISION:	DHAMDAHA LENGTH: 8.430 KM	
NAME OF THE ROAD:	Pirsaha (goriyer) to Bhawasipus	
SCHEME/PROGRAMME:	MAINTENANCE	
PACKAGE No:	ROAD ID No.: 21105302053	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL.NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
Α	ROAD JUNCTION CONDITION	5
В	CONDITION FO SURFACING	S
C	RIDING QUALITY	. 5
D	ROAD CAMBER	S
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	yes
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N.A
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	yes
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N·A .
В	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N. A
С	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A
3	ROAD FURNITURE	
Α	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD NARKING ARE PROVIDED AND MAINTAINED	Yes
4	COMPLIANCE HISTORY	
Α	STATUS OF ATR's & ANY OTHERS	NO ANY ATR
ERALL RATING		
	SATISFACTORY(S)	S
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI) UNSATISFACTORY(U)	-

NAME: Kamer Naryan sharma.
DESIGNATION: Junior Engineer

Scanned with CamScanner