FIELD INSPECTION REPORT

Date of Inspection: 31/2.20 District: Katihar.					
Division · Katihar					
Name of Road:		Dyolo sood to Byo Maijas up byo popo			
Scheme/ Programme: MA		MAINTENA	MAINTENANCE		
Packa	ge No. MA-N1 19-2	2 Sold your	Road ID No. 2110550 1015		
		Onging/Completed/Under Maintenance			
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance			
Sl.No Parameters to be Cl		neters to be Checked	Remarks		
1	Pavement			- Tellial Ro	
a)	Road Junction Condition			S/U NV	
b)	Condition of Surfacing			S/U Nu	
c)	Riding Quality			S/U N	
d)	Road Camber			S/U N	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No (\)	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No N	
g)	Compaction of flank/slpoe & raincuts if any			Yes/No N	
2	Cross Drainage				
a)	Condition of headwalls inn Humepipe culverts including its painting			S/SRI/U N	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts				
c)	Condition of railings/slabs//approach for Bridges			S/SRI/U N	
3	Road Furniture			s/sri/u	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			LYes/No	
4	Compliance History				
a)	Status of ATR & any others			Na	
A		Satisfactory (S	5)	110	
			ut requires Improvement(SRI)	5	
		Unsatisfactory			

Name: Mitan 1 4 4 4 4 Med Degisnation- Junior Common R.W.D. Works Div., Katihar