

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	District: Kahlua
Division : Barsoi	Length (km): 3.105 km
Name of the Road: Salmari kudum PWD Road to Mallikpur via Govindpur	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U-NA ✓
b)	Condition of Surfacing	S/U-NA ✓
c)	Riding Quality	S/U-NA ✓
d)	Road Camber	S/U-NA ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No NA ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U-NA ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U-NA ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U-NA ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	N/A (Recently work has been started)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

03/12/2020
(Signature)

NAME: GIRJA NAND SINGH

DESIGNATION: ASSISTANT ENGINEER