## FIELD INSPECTION REPORT

		2090 District: Katihar.	
	on : Katihar	Length (KM): 2.10 K.M.	
Name of Road:		sampli gan to chandpur PWD Road.	
Scheme/ Programme:		MAINTENANCE	
Packa	ge Nom/R-N/19-3	Katilantos Road ID No. 211056010EF	
	of the Project:	Onging/Completed/Under Maintenance	
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
SI.No		Parameters to be Checked	Remarks
1	Pavement		7
a)	Road Junction Cond	lition	S/U NA
b)	Condition of Surfacing		S/U NA
c)	Riding Quality		S/U NA
<u>d)</u>	Road Camber		S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Payement		Yes/NoNA
f)	Contraction Joints provided or not (CC Pavement)		Yes/No NA
g)	Compaction of flank/slpoe & raincuts if any		Yes/No Pas
2	Cross Drainage		,
a)	Condition of headwalls inn Humepipe culverts including its painting  S/SRI/U		S/SRI/U NA
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/UNA
c)		Condition of railings/slabs//approach for Bridges  S/SRI/UA	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		✓Yes/No Par
4	Compliance History		
a) Status of ATR & any others		others	No
Overall Grading:		Satisfactory (S)	ತ
		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	

Name: PAPPU KUMAR Degisnation- J. E/ Sameli

R.W.D. Works Div., Katihar

2. 12. 2020 (Signature)